

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- BLURRY OR ILLEGIBLE TEXT
- SKEWED/SLATED IMAGES
- COLORED PHOTOS
- BLACK OR VERY DARK BLACK AND WHITE PHOTOS
- UNDECIPHERABLE GRAY SCALE DOCUMENTS


IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




2/23

【Fig.2】




【Fig.3】




4/23

【Fig.4】




5/23

【Fig.5】




6/23

【Fig.6】



7/23


【Fig.7】



For 660-4919960

8/23

【Fig.8】




$$(\text{eccentricity}) = \frac{L0 - L1}{L0}$$

Actual ground contact length L1 is smaller than L0 (when eccentricity is zero) because of eccentricity.


9/23

【Fig.9】




10/23

【Fig.10】




【Fig.11】




12/23

【Fig.12】





【Fig.13】





14/23

【Fig.14】









19/23

【Fig.19】






FIG. 19


【Fig.20】



【Fig.21】



【Fig. 22】



【Fig.23】

